WHS-PRO-008 Asbestos Management Procedure Appendix 2 – Assessment Warning labels



Building contains asbestos (on Douglas campus)					
ize A6, 148 x 105mm					
Material outdoor vinyl, UV resistant clear laminated					
Black text on sunflower yellow as per AS1319					
	\SBESTOS				
CONTAINING MATERIAL EXISTS AT THIS					
BUILDING					
	PRIOR TO COMMENCING WORK				
100	PRIOR TO COMMENCING WORK NSULT ASBESTOS REGISTER LOCATED AT				
	NSULT ASBESTOS REGISTER LOCATED AT				
E	NSULT ASBESTOS REGISTER LOCATED AT STATE DIRECTORATE RECEPTION, BUILDING 57				
ES	NSULT ASBESTOS REGISTER LOCATED AT STATE DIRECTORATE RECEPTION, BUILDING 57 ECURITY OFFICE, BUILDING 29				
ES	NSULT ASBESTOS REGISTER LOCATED AT STATE DIRECTORATE RECEPTION, BUILDING 57				
E S O	NSULT ASBESTOS REGISTER LOCATED AT STATE DIRECTORATE RECEPTION, BUILDING 57 ECURITY OFFICE, BUILDING 29				



WHS-PRO-008 Asbestos Management Procedure Appendix 2 – Assessment Warning labels

Label Specification		
Description	Building contains asbestos (Off Campus Buildings)	
Size	A6, 148 x 105mm	
Material	Outdoor vinyl, UV resistant clear laminated	
Colour	Black text on sunflower yellow as per AS1319	

ASBESTOS

CONTAINING MATERIAL EXISTS AT THIS BUILDING

PRIOR TO COMMENCING WORK CONSULT ASBESTOS REGISTER LOCATED

ONSITE:

OR PHONE (07) 4781 4444

AN "ASBESTOS" PERMIT IS REQUIRED FOR WORK ON MATERIAL CONTAINING ASBESTOS

Version: 20-1	Approval Date: 17/06/2020	Next Review Date: 17/06/2023	Page 2 of 2
---------------	---------------------------	------------------------------	-------------